Weighing Steps:

1. After it is powered on, hang the item on the hook and the weight will be displayed.
2. When the weight is stable, the data will be locked and the LCD will display 'HOLD'. You will near a beep.
3. Put down the item and read the accurate weight on the screen.
4. Press ON/TARE button to unlock the data and you will be able to weigh items again.
5. If the total weight of the item (including the container when using TARE function) is greater than 40kg, the scale will show 'ERR'. Remove the items immediately to avoid damaging the scale.

Tare Function:

1. Hang the container onto the hook.
2. Press the ON/TARE button to reset to 0g.
3. Put the item to be weighed into the container.

Power Off:

- The scale will automatically power off approximately 15 seconds after you finish weighing.
- If you want to turn the scale off manually, press the ON/TARE button to unlock it first, then press and hold the ON/TARE button for 2 seconds to turn off.

IMPORTANT:

- Ensure to keep the scales "Off" when not in use.
- Ensure to remove the batteries from the scales when in storage.
- Never get the scales wet, including the internal parts and the batteries.
- Never attempt to open, repair or modify any part of the scales.